Tacfast[®] Carpet Tile System


Simplifies installation and provides for flexibility with a user and environment-friendly product

The concept is base on a hook and loop fastening system using carpet tile which has a loop material covering its entire underside. Hook tapes are fastened to the sub-floor by means of a pressure-sensitive adhesive. The hook and loops 'engage' and form a mechanical bond, which holds the carpet in place. Available with these products;

- Cross Stitch
- Enterprise

Diplomat


- Senator Soft-Step
- Dominator





portico

Solutions that Simplify. 1+ 877 285 8899 · www.porticosystems.com



Tacfast®

> HOOK & LOOP CARPET TILE SYSTEM

SUGGESTED USES (Not limited to)

In spaces where tiles are likely to shift or have large machinery driven over carpet tiles.

Construction:

Continuous Inject Mold Material:

Polypropylene
No. of Hooks:
Hook Pitch (P1):
Hook Pitch (P2):
Hook Weight:
Thickness:

Continuous Inject Mold
Polypropylene
10.055" (1.4mm)
10.055" (1.4mm)
10.023" (0.6mm)
10.027" (0.7mm)
10.035" (0.9mm)

LIMITED WARRANTY
Full Commercial Warranty

5 year

Summary of Warranty:

Portico Systems warrants TacFast® Carpet Tile System against wear for a period of 5 years in a commercial application. This warranty applies only to material that is properly installed and maintained, while being used as intended and recommended. If the defect is covered by this warranty and is reported to Portico Systems within the Warranty period, Portico Systems will supply new material of same or similar grade to repair or replace the defective material.

- Wear
 - Defined as complete removal of wear layer, pattern and color due to wear from normal traffic and maintenance. If the wear occurs within 1 year from date of purchase, Portico Systems will provide replacement materials or repair, of only the effected area.
- · Manufacturing Defects

Portico Systems warrants Cross Stitch Carpet Tiles materials are free from manufacturing defects and will replace defective floor covering and reasonable installation costs for a period of up to five [5] years from date of purchase. Portico Systems will not pay labor costs to repair or replace materials that defects were apparent before or at the time of installation.

- · Other Limitations
 - · This warranty is non-transferable
 - Manufacturing defect must be reported within 3 months from date of purchase.
 - · This Warranty covers only properly installed & maintained floors
 - Portico Systems excluded and will not pay for any consequential or incidental expenses.
 - Portico Systems reserves the right of final judgment and may refuse claims in certain instances.

INSTALLATION (TILE)

Before laying tiles, it is recommended they are stored at room temperature 60°F-70°F (15°C-20°C). The tiles can be loose laid on flat, dry floors free from impurities such as oil, grease etc. Cracked floors should be filled, and uneven floors covered with hardboard. Dusty floors should be primed. Because of the high insulation value of these tiles it is not recommended they be laid when under-floor heating systems are in use. On very large installations, it is advisable to secure 1 in 5 rows with double-sided tape Where tiles are to be used under caster chairs, tiles should be fully secured. The tiles may be laid by marking across in the center of the room and working outwards from this, the marker cross may be moved to facilitate these of full tiles in doorways, etc. Tiles must be laid by turning alternate tiles through 90 degrees to obtain a checker pattern. An arrow on the back of each tile indicates the pile direction. Only tiles with the same batch number should be laid together.

MAINTENANCE

Regular vacuuming (Weekly in low-traffic areas, and daily or twice daily in areas with higher traffic) with a motor-driven brush and beater bar can remove up to 80% of surface dirt, and is the easiest way to prolong the life of your carpet.

Regular vacuuming is key to maintaining your carpet, but eventually the carpet color dulls from dirt and grime stuck in the fibers. The dirt is then carried further into the building to form more soil reservoirs. Additionally, the oil content (15%) of the soil causes particles to stick to carpet fiber and resist vacuuming. To restore the carpet to its best condition, frequent light cleaning gives the best result and is often very cost effective.

IMPORTANT NOTICE

Sample swatches have been cut from an overall design; decoration and shade may vary.

YOUR AUTHORIZED SALES REPRESENTATIVE:



experience it for yourself Talk with your sales representative or request samples at samples at samples.

^{*}For a copy of the full warranty please ask for a warranty sheet